

# BluOS™

## iPort Driver Manual

©2018 LENBROOK INDUSTRIES LIMITED

All rights reserved.

No part of this publication may be reproduced, stored or transmitted in any form without the written permission of Lenbrook Industries Limited. While every effort has made to ensure the contents are accurate at the time of publication, features and specifications may be subject to change without prior notice.

<b>Revision History</b>			
<b>Version</b>	<b>Date</b>	<b>Author</b>	<b>Description</b>
1.0.0	03/14/2018	Gary S.	Initial release.

# Table of Contents

---

---

1.0 Introduction .....	4
2.0 Installation .....	5
2.1 Configuring BluOS .....	5
3.0 Using the Driver .....	6
4.0 Support .....	7
5.0 Known Issues .....	8

# 1.0 Introduction

---

This document describes how to install, configure and use the BluOS iPort driver.

The following BluOS players are supported with this driver:

- Bluesound Node 2, Powernode 2, Pulse Flex, Pulse Mini, Pulse 2, Pulse Soundbar and Vault 2.
- NAD M50, M50.2, CI580 and CI720.
- NAD C390DD, M12, M32, C368 and C388 (with optional MDC BluOS or MDC BluOS 2 card).
- NAD T757 and T758 (with optional VM130 MDC card and license).
- NAD M15HD, M17, T175, T187, T755, T765, T775, T777, T785 and T787 (with optional VM300 MDC card and license).

BluOS 2.16.2 or higher is required.

The following iPort devices are supported:

- Surface Mount with Buttons

Configuration of BluOS to work with iPort devices is done using the BluOS Integration Utility.

## 2.0 Installation

---

Ensure that your players are running the latest version of BluOS firmware.

Download and install the BluOS Integration Utility on a Windows or macOS computer.

## 2.1 Configuring BluOS

---

Use the BluOS Integration Utility to configure BluOS.

## 3.0 Using the Driver

---

A BluOS player is assigned as the BluOS Hub. The BluOS Hub manages all communications with other BluOS players. Ensure that the BluOS Hub is available on the network.

When the BluOS Hub is powered on, the iPort communication services are automatically started. There is no configuration setting to turn iPort communication services on or off.

# 4.0 Support

---

For technical support issues, contact BluOS technical support at <http://support.bluos.net> or email [support@bluos.net](mailto:support@bluos.net).

# 5.0 Known Issues

---

The following issues are known to exist.

Driver Version	Issue	Workaround
	None	